

FIG. 1





FIG. 2






FIG. 4




FIG. 5




FIG. 7




FIG. 8




FIG. 9




FIG. 10



eport							1
Prairie B	的问题基	100%	Toa 4	1002			
					ACE OF SECURITY		erse.
		22 <u>016 y ruses (2 v. 18</u> 68)	170211000	ar garanaga	griftingsgrift by the programme and the second of the		a
		ReliSord	th Mobil	lity Inc			
ECP: 7	BellSouth Mobility, Inc. RF Engineering					3/26/2001 14	
DCS: 1	System Design Plan					LynKeeCR	
							-
SITE INFORMATION						: 027 23 40.1	_
	Number: University!					2: 082 27 13.3	4
	Address: 8101 Coope Zipcode Bradenton,				Type of Structure Ground Elevation (AMSL)		
	County: Manatee	ri Jazon			Support Height (AGL)		
L							=
REGULATORY			=4.4.0.1	00 000	ne Med Intesity Strok		
	027 23 40.15			99.aso.0953.c 5.18 meters	o/W Pai		
	082 27 13.34		nuct Height		High Intensity Strob		
NAD	0			69.19 maters	Red Braco		
FAA Ground AMSL			ecistration		Duel Llei	let 0	
FAA Struct Height FAA Total AMSL			nt Distance t Direction				
TAR I VIII MANUE		nupu.	·				_
FACES							-
FACES							
	Alpka 0	Beta 120	-	240			
Asizenth		1		240			
RX Antenna	1,625	1,625	-	1.625			
RX Line-Type RX Manufacturer	Andrews	Andrews	-	Andrews			
	——	S19HA-11015-0DG	S19HA-11				
RX Model	S19HA-11015-0DG	219HA-11012-013G	313UA-11	110			
POPPER NAME	CANADA CARENTAL	F-174-174-175	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	(4)740740			Ć

FIG. 11